

Team 9: Pierce Ground Floor Lab Inspection Report
Inspected: March 6, 2013

Members: Elisa Maldonado (Chair), Peter Doherty, Ankita Shastri

CROZIER GROUP

Safety officer: Wenqi Zhu

G13:

ER guide not taped to wall.

Not all liquid containers labeled.

One flammable liquid container out in open.

No secondary container in Satellite Accumulation Area.

Sharps out in open - store in cork or PDMS.

Big pile of cardboard boxes near door - fire hazard?

SEAS TEACHING LABS

Safety officers: Sara Hamel and Peter Kjeer

G11:

No emergency eyewash.

Previous evidence of beverage in lab: Nalgene bottles on desk.

G12 a,b:

No problems.

G6 a,b:

Remember to check hazard box on hazardous waste label.

G7 b,c:

Acetylene (flammable gas) present, but not in ventilated cabinet or enclosure.

Ammonium persulfate (oxidizer) stored together with sulfuric acid and acetic acid in same secondary container in hood.

NaOH and HCl in same secondary container in Satellite Accumulation Area.

Containers in SAA were not appropriately labeled: waste name was abbreviated and hazard boxes were not checked.

Outlet near sink not GFCI.

Electrical panel obstructed by gloves.

G16 a,b,c:

Paraformaldehyde (solid form) not in flammables cabinet.

Acid in same secondary containment with other chemicals in hood.

G17a:

No problems.